

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 08/16/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 1200, 08/16/12 – 1200, 08/23/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Aerial Field Observer	Houston, TX
8. Activity Log			
Time	Major Events		
	Operational Observation:		
0630	<ul style="list-style-type: none"> Arrived at the ICP 		
0700	<ul style="list-style-type: none"> Attended the weekly IAP brief out. 		
0730	<ul style="list-style-type: none"> Began the production of the Situational Photolog for the EPA C&G. 		
0800	<ul style="list-style-type: none"> Attended the EPA C&G meeting. 		
0930	<ul style="list-style-type: none"> Arrived at E4 Boat Launch and launched the boat. Morrow Lake southeastern cove observed scattered sliver sheen. Morrow Lake Delta observed a crew removing debris from Boom E. Morrow Lake Delta observed sheen collecting along Boom C. MP36.5 RDB observed sheen ribbons. There was not enough sheen to warrant the sweep boat. MP36.25 LDB observed sheen ribbons. There was not enough sheen to warrant the sweep boat. MP28.25 Oxbow observed a crew performing the monthly sediment trap monitoring. MP28.25 observed heavy sheen when the boat reversed from the bank. 		
10:45	<ul style="list-style-type: none"> Weather stand down returned to E4 Boat launch. 		
11:30	<ul style="list-style-type: none"> Inspected Ceresco Dam from the dam. Sheen observed collecting at the boom. The decontamination station was not present. Observed sheen within the portage below the dam. 		
1230	<ul style="list-style-type: none"> Returned to the ICP. 		
1400	<ul style="list-style-type: none"> Launched out of C0.4. Observed sheen at MP5.25 – MP5.63 along the LDB. MP5.63 LDB observed heavy sheen. MP4.75 LDB observed ribbons of silver sheen. We traced the sheen up river to the lower extent of the former Island F. When patches of silver sheen were observed. When the boat reversed out of the area a considerable amount of sheen was generated. 		
1530	<ul style="list-style-type: none"> Pulled the boat and return to the ICP. 		
	Planning Activities:		
	<ul style="list-style-type: none"> Completed 214 Prepared and distributed Daily Situation Unit Photo Log. 		
9.	Prepared by (Name and Position) Matthew Haak, Situation Unit, USEPA-START		